

Project Name:Gold King Mine

Site Location:

Silverton, San Juan County, Colorado

Project No. 0001/1408-01

Photo No.

Date: 08/04/2015

Direction Photo Taken:

North

Description:

Beginning investigation into collapsed adit.



Photo No. 2

Date: 08/04/2015

Direction Photo Taken:

North

Description:

Excavated next to DRMS-installed culvert, water muddy from soil disturbance.



Page 1 of 27



Project Name:

Gold King Mine

Site Location:

Silverton, San Juan County, Colorado

Project No.

0001/1408-01

Photo No.

Date: 08/04/2015

Direction Photo Taken:

Down

Description:

Seepage from soil next to piping.



Photo No.

Date: 08/04/2015

Direction Photo Taken:

Down

Description:

Seepage next to the pipe is clear until entering disturbed soil.





Project Name:Gold King Mine

Site Location:

Silverton, San Juan County, Colorado

Project No. 0001/1408-01

Photo No. **5**

Date: 08/04/2015

Direction Photo Taken:

North

Description:

DRMS looking at adit excavation progress.



Photo No.

Date: 08/04/2015

Direction Photo Taken:

West

Description:

Water minimally murky from disturbed soil and water entering the North Fork from site.



Page 3 of 27



Project Name:

Gold King Mine

Site Location:

Silverton, San Juan County, Colorado

Project No.

0001/1408-01

Photo No. 7

Date: 08/04/2015

Direction Photo Taken:

South/Down

Description:

Hay bales installed as filter for sediment in North Fork.



Photo No.

Date: 08/04/2015

Direction Photo Taken:

Northwest

Description:

Continuing excavation at the collapsed adit, no solid bedrock found for tunnel support.



Page 4 of 27



Project Name:

Gold King Mine

Site Location:

Silverton, San Juan County, Colorado

Project No. 0001/1408-01

Photo No.

Date: 08/04/2015

Direction Photo Taken:

Northeast

Description:

First signs of adit, support pillar with lagging.



Photo No. 10


Date: 08/04/2015

Direction Photo Taken:

East

Description:

Water of the North Fork just upstream of Cement Creek.



Page 5 of 27



Project Name:

Gold King Mine

Site Location:

Silverton, San Juan County, Colorado

Project No. 0001/1408-01

Photo No. 11

Date: 08/04/2015

Direction Photo Taken:

East

Description:

Water of the North Fork just upstream of Cement Creek.



Photo No.

Date: 08/04/2015

12

Direction Photo Taken:

North

Description:

Collapsed supports uncovered above anticipated adit, no sign of bedrock above the adit area.



Page 6 of 27



Project Name:Gold King Mine

Site Location:

Silverton, San Juan County, Colorado

Project No. 0001/1408-01

Photo No. 13

Date: 08/05/2015

Direction Photo Taken:

North

Description: Adit conditions the morning of 8/5.




Photo No. 14

Date: 08/05/2015

Direction Photo Taken:

Northeast

Description:Excavating material above the collapsed adit.





Project Name:

Gold King Mine

Site Location:

Silverton, San Juan County, Colorado

Project No. 0001/1408-01

Photo No. 15

Date: 08/05/2015

Direction Photo Taken:

North

Description:

Bedrock found above the anticipated adit.



Photo No. 16

Date: 08/05/2015

Direction Photo Taken:

North

Description:

Cleaning out excavated material, small leak.



Page 8 of 27



Project Name:Gold King Mine

Site Location:

Silverton, San Juan County, Colorado

Project No. 0001/1408-01

Photo No. 17

Date: 08/05/2015

Direction Photo Taken:

North

Description:

Small leak close up.



Photo No. 18

Date: 08/05/2015

Direction Photo Taken:

North

Description: Hole starting to give way to flow.



Page 9 of 27



Project Name:

Gold King Mine

Site Location:

Silverton, San Juan County, Colorado

Project No. 0001/1408-01

Photo No. 19

Date: 08/05/2015

Direction Photo Taken:

Northeast

Description:

Adit flow increasing.



Photo No. 20

Date: 08/05/2015

Direction Photo Taken:

Northeast

Description:

Water flooding out at increased rate.



Page 10 of 27



Project Name:

Gold King Mine

Site Location:

Silverton, San Juan County, Colorado

Project No. 0001/1408-01

Photo No. 21

Date: 08/05/2015

Direction Photo Taken:

West

Description:

Water flowing along access road and across waste dump.



Photo No. 22

Date: 08/05/2015

Direction Photo Taken:

Southeast

Description:

Water flowing over the edge of the waste dump and collapsing the edge.



Page 11 of 27



Project Name:

Gold King Mine

Site Location:

Silverton, San Juan County, Colorado

Project No. 0001/1408-01

Photo No. 23

Date: 08/05/2015

Direction Photo Taken:

Southwest

Description:

Exit route starting to collapse



Photo No. 24


Date: 08/05/2015

Direction Photo Taken:

Southeast/Down

Description:

Edge of the tailings dump collapsed, suburban trapped and half submerged in center of photo.



Page 12 of 27



Project Name:Gold King Mine

Site Location:

Silverton, San Juan County, Colorado

Project No. 0001/1408-01

Photo No. 25

Date: 08/05/2015

Direction Photo Taken:

Northeast

Description:Gold King adit exposed.




Photo No. 26

Date: 08/05/2015

Direction Photo Taken:

Southeast

Description:

Water flow washing out the existing road. Note Suburban in left side of photo.



Page 13 of 27



Project Name:

Gold King Mine

Site Location:

Silverton, San Juan County, Colorado

Project No. 0001/1408-01

Photo No. 27

Date: 08/05/2015

Direction Photo Taken:

North

Description:

Exposed adit, roughly 10 feet wide by 15 feet high.




Photo No. 28


Date: 08/05/2015

Direction Photo Taken:

North

Description:

pH of discharge water is approximately 4 to 4.5.



Page 14 of 27



Project Name:

Gold King Mine

Site Location:

Silverton, San Juan County, Colorado

Project No. 0001/1408-01

Photo No. 29

Date: 08/05/2015

Direction Photo Taken:

Northeast

Description:

Excavator redirecting water into existing half-pipe channel.




Photo No. 30

Date: 08/05/2015

Direction Photo Taken:

Southeast/Down

Description:

Collapsed portion of waste dump and road wash out.



Page 15 of 27



Project Name:

Gold King Mine

Site Location:

Silverton, San Juan County, Colorado

Project No. 0001/1408-01

Photo No. 31

Date: 08/05/2015

Direction Photo Taken:

Northeast

Description:Adit area after regrading.




Photo No. 32


Date: 08/05/2015

Direction Photo Taken:

North

Description:

Exposed adit and redirected flow, flow is beginning to subside.



Page 16 of 27



Project Name:

Gold King Mine

Site Location:

Silverton, San Juan County, Colorado

Project No. 0001/1408-01

Photo No.

Date: 08/05/2015

Direction Photo Taken:

East

Description:

Redirected flow into existing half culvert channel.




Photo No. 34

Date: 08/05/2015

Direction Photo Taken:

North

Description: Closeup of adit.



Page 17 of 27



Project Name:

Gold King Mine

Site Location:

Silverton, San Juan County, Colorado

Project No. 0001/1408-01

Photo No. 35

Date: 08/05/2015

Direction Photo Taken:

West

Description:

Excavator beginning work to secure safe exit route for equipment, vehicles, and personnel.




Photo No. 36

Date: 08/05/2015

Direction Photo Taken:

East

Description:

Existing flow channel at maximum capacity.



Page 18 of 27



Project Name:

Gold King Mine

Site Location:

Silverton, San Juan County, Colorado

Project No. 0001/1408-01

Photo No. 37

Date: 08/05/2015

Direction Photo Taken:

Southwest/Down

Description:

Excavator progress on fixing access road to create a safe exit route.



Photo No. 38


Date: 08/05/2015

Direction Photo Taken:

East

Description:

Existing culvert flows subsiding minimally.



Page 19 of 27



Project Name:

Gold King Mine

Site Location:

Silverton, San Juan County, Colorado

Project No. 0001/1408-01

Photo No. 39

Date: 08/05/2015

Direction Photo Taken:

North

Description:

No changes visible in adit structure or supports. Sloughing of materials inside the mine can be heard.




Photo No. 40

Date: 08/05/2015

Direction Photo Taken:

South/Down

Description:

Excavator progresses to washed out North Fork crossing.



Page 20 of 27



Project Name:

Gold King Mine

Site Location:

Silverton, San Juan County, Colorado

Project No. 0001/1408-01

Photo No. 41

Date: 08/05/2015

Direction Photo Taken:

Southwest/Down

Description:

Noted visitor to the site, unknown person, walked up to excavator at North Fork crossing and then back to vehicle.



Photo No.

Date: 08/05/2015

NO. 08/05/20

Direction Photo Taken:

Southwest/Down

Description: Visitor leaving.



Page 21 of 27



Project Name:

Gold King Mine

Site Location:

Silverton, San Juan County, Colorado

Project No. 0001/1408-01

Photo No. 43

Date: 08/05/2015

Direction Photo Taken:

South/Down

Description:

Excavator continues to fix access road. Continued high flow is slowing progress.



Photo No. 44


Date: 08/05/2015

Direction Photo Taken:

East

Description:

Half culvert flow continues to subside.



Page 22 of 27



Project Name:

Gold King Mine

Site Location:

Silverton, San Juan County, Colorado

Project No. 0001/1408-01

Photo No. 45

Date: 08/05/2015

Direction Photo Taken:

North

Description:

Water levels lowering at adit entrance, no visible changes to structure.




Photo No. 46

Date: 08/05/2015

Direction Photo Taken:

West

Description:

Flight for life Helicopter coming up the valley to pick up a person who crashed a vehicle on Corkscrew Pass, not related to this event.



Page 23 of 27



Project Name:

Gold King Mine

Site Location:

Silverton, San Juan County, Colorado

Project No. 0001/1408-01

Photo No. 47

Date: 08/05/2015

Direction Photo Taken:

Southwest

Description:

Close up of Flight for Life.



Photo No. 48

Date: 08/05/2015

Direction Photo Taken:

Northeast

Description:

Flow path from adit, water flow appears to have stabilized around 1400.



Page 24 of 27



Project Name:

Gold King Mine

Site Location:

Silverton, San Juan County, Colorado

Project No. 0001/1408-01

Photo No. 49

Date: 08/05/2015

Direction Photo Taken:

North

Description:

pH measured at approximately 4.5.



Photo No. **50**

Date: 08/05/2015

Direction Photo Taken:

Southwest/Down

Description:

DRMS arrives back on site, had visited the site around 0930 to check on progress of investigation, left approximately 1030, prior to blowout.



Page 25 of 27



Project Name:

Gold King Mine

Site Location:

Silverton, San Juan County, Colorado

Project No. 0001/1408-01

Photo No. **51**

Date: 08/05/2015

Direction Photo Taken:

North

Description:

Looking up from the toe of the Gold King waste dump directly south of the adit.




Photo No. **52**

Date: 08/05/2015

Direction Photo Taken:

Northeast

Description:

Gold King Mine tailings dump after water discharge.





Project Name:

Gold King Mine

Site Location:

Silverton, San Juan County, Colorado

Project No. 0001/1408-01

Photo No. 53

Date: 08/05/2015

Direction Photo Taken:

East

Description:

Looking east across Cement Creek from County Road 10 to excavator fixing County Road 52 at North Fork crossing just south of Red and Bonita Mine.



Photo No. **54**

Date: 08/05/2015

Direction Photo Taken:

East

Description:

Cement Creek crossing at Gladstone.





Project Name:Site Location:Project No.Gold King MineSilverton, San Juan County, Colorado0001/1408-01